

Message

From: Hanchett, James (DPH) [/O=COMMONWEALTH OF MASSACHUSETTS/OU=MASSMAIL-01/CN=RECIPIENTS/CN=JAMES.HANCHETT]
Sent: 2/29/2012 1:16:46 PM
To: Lobik Stephen [slobik@facil.umass.edu]
Subject: AC/Heating Unit

Hi Steve,

I had a guy from Johnson Controls look at our heating unit. There is not enough pressure to push condensate up 18 inches. It does not help to increase steam pressure because control valves will throttle it down. The solution is to not push condensate up 18 inches of pipe. Smallest amount is best. What can be done?

Jim Hanchett
Amherst Drug Lab
Room N251 Morrill I
637 North Pleasant Street
Amherst, MA 01003
Phone 413-545-2607
Fax 413-545-2608
Cell [REDACTED]